Water-slide joint sealant degradation in high UV

IA-2026-004 - technical | Issued 2026-05-19

Bulletin no.	IA-2026-004
Category	technical
Manufacturer	Fibreglass slide suppliers
Ride / device	Body and tube slides
Jurisdiction	Rajasthan, Tamil Nadu

Sealant at fibreglass slide joints can harden and crack after prolonged UV exposure, creating sharp edges and leaks. Inspect joints monthly in peak season and re-seal with the manufacturer's specified product.

SAMPLE DOCUMENT - seeded placeholder content for layout. Replace with the official IAARSO document.